







① 	② 	③ 	④ 	⑤ 	⑥ 	⑦ 	⑧ 	⑨ 	⑩ 	⑪ 
3	3	2	2	2	2	1	1	2	3	3




⑫ 	⑬ 	A  M6*20	B  M6*35	C  M6*45	D  $\Phi 14 * \Phi 6.5 * 1.0$	E 	F 	G 	H  M6*40	I  M6*30
2	1	4	19	6	45	1	1	8	4	4





B		D	
M6*35	4	Φ14*Φ6.5*1.0	4

×2




B		C		D	
M6*35	2	M6*45	2	Φ14*Φ6.5*1.0	4


× 2





×2




A		B		D	
M6*20 4		M6*35 4		Φ14*Φ6.5*1.0 8	



B	 M6*35	3	C	 M6*45	2	D	 Φ14*Φ6.5*1.0	5
---	--	---	---	--	---	---	---	---





I		M6*30	4
D		Φ14*Φ6.5*1.0	16
H		M6*40	4
G			8

